

General Environmental Incident Summary

Incident: 5891 **Date/Time Notice:** 10/29/2018 1007 **DEM Incident No:**
Responsible Party: Wolla Trucking
Date Incident: 10/29/2018 **Time Incident:** 0845 **Duration:** 5 minutes
County: Williams **Twp:** 154 **Rng:** 100 **Sec:** 35 **Qtr:**
Lat: 48.11769 **Long:** -103.51050 **Method:** Interpolation from map
Location Description: County road 9 south of 1804

Submitted By: Jason Wolla **Affiliation:**
Address: 6231 117th Ave NW
PO Box 830
City: Ray **State:** ND **Zip:** 58849

Received By:

Contact Person: Jason Wolla
Po box 830
Ray, ND

Distance Nearest Occupied Building: **Release Contained:** No

Type of Incident: Tank Leak

Description of Released Contaminant: Water/oil

Volume Spilled: 8.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Hose fell off truck, Cap broke off hose. Apparently driver did not have valve closed.

Risk Evaluation:

Paved road

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

Small amount could leave the roadway onto soil with rain

Action Taken or Planned:

Notified sheriffs immediately, notified William's county highway and disaster relief immediately. Shut down road. Washing up spill. Not much to excavate as it is contained to the roadway.

Wastes Disposal Location: Furlong syverson disposal

Agencies Involved: Local Law Enforcement, Local Emergency Manager

Updates

Date: 10/30/2018 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

According to the environmental incident report, the release of water and oil was not contained. Further follow-up is needed.