General Environmental Incident Summary

Incident: 5947 *Notice:* 1/4/2019 1610 *Occurred:* 1/4/2019 0130

DEM Incident No: No Further Action:

Responsible Party: Schlumberger OST

County: Williams

Twp Rng Sec Qtr: 154 101 20

Lat Long + Method: 48.14269 -103.70290 Interpolation from map

Location Description: 5922 Dakota Parkway west

Submitted By Info: Jesse Smith

QHSE Rep.

5922 Dakota Parkway west

Williston ND

Received By Info:

Contact Info: Jesse Smith

5922 Dakota Parkway west

Williston ND 58801

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Antifreeze leak

Release Contained: Yes
Reported to NRC: Unknown

Contaminant: Shell Rotella ELC pre-diluted 50/50 Antifreez

Volume of Release: 25 gallons

Duration of Release: 2 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance:NoNumber of Fatalities:0Number of Injuries:0

Cause of Incident:

Hose failure and spill of 25 gallons antifreeze on the ground

Risk Evaluation: Health if injested

Potential Env. Impacts:

None, Spill cleaned up

Action Taken/Planned:

Spill was absorbed with absorbent and placed in a quarantined for disposal in approved site

Wastes Disposal Location:

TBD post analysis.

Other Agencies Involved:

Updates

Date: 1/4/2019 Status: No Further Action Requested

Author: DeVries, Taylor

Notes:

According to the incident report, the release of antifreeze was contained to the responsible party's yard. Spoke with responsible party about clean up. No further follow-up needed at this time.

Updated Volume: None at the time of this update