

General Environmental Incident Summary

Incident: 7011 **Notice:** 3/9/2019 1130 **Occurred:** 3/8/2019 2330

DEM Incident No:

No Further Action:

Responsible Party: Plains Marketing

County: Billings

Twp Rng Sec Qtr: 139 101 11

Lat Long + Method: 46.87157 -103.38920 Navigation quality GPS

Location Description: 13940 sully Creek Road

Submitted By Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Received By Info:

Contact Info: Daniel Holli
P.O. Box 708
Belfield ND 58622

Affected Medium: 03 - soil

Near. Occupied Bldg: 1 Miles

Type of Incident: Valve leak

Release Contained: Yes

Reported to NRC: No

Contaminant: Crude oil condensate

Volume of Release: 2 barrels

Duration of Release: 15 minutes

Agriculture Related: No

EPA Extremely Hazardous Substance: No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Valve was leaking while Diamond B contract truck driver unloaded condensate at the Fryburg Station.

Risk Evaluation:

None

Potential Env. Impacts:

soil

Action Taken/Planned:

Impacted snow and soil will be picked up into containment

Wastes Disposal Location:

Approved special waste landfill

Other Agencies Involved:

Updates

Date: 3/9/2019 **Status:** Reviewed - Follow-up Required

Author: Martin, Russell

Notes:

Release due to valve leak, at a non-E&P exempt facility, according to the report. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 4/9/2019 **Status:** Inspection

Author: Martin, Russell

Notes:

4/5/2019 at 11:41, on location. Met with personnel at site who indicated the locations where Diamond B would have been unloading. No visible staining under the equipment, and there is a covered rolloff on location which may contain the impacted snow and soil. Report contact will be supplying disposal receipts. No further follow-up needed at this time.

Updated Volume: None at the time of this update