

Updates

Date: 5/13/2019 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted the surrounding area. Follow-up is necessary.

Updated Volume: None at the time of this update

Date: 6/4/2019 **Status:** Inspection

Author: O'Gorman, Brian

Notes:

Arrived at the GPS coordinates provided in the report at 14:34. 80 degrees F, Mostly Sunny, Northwest wind 20-30 mph. Observed the area and did not notice any petroleum stained vegetation on the driving surface near the GPS location. No further on-site inspection needed. Follow-up with phone communications to make sure the area inspected was correct. Photos added to the incident folder.

Updated Volume: None at the time of this update