

General Environmental Incident Summary

Incident: 8072

Notice: 5/15/2019

Occurred: 5/13/2019

DEM Incident No:

No Further Action:

Responsible Party: Andeavor Logistics

County: McKenzie

Twp Rng Sec Qtr: 153 95 3

Lat Long + Method: 48.10518 -102.88790 Interpolation from map

Location Description: 48.105176135604374, -102.88785353275544

Submitted By Info: Alan Thompson
500 Old Red Trail NE
Mandan ND 58554

Received By Info:

Contact Info: Aaron Oakland
2972 108th S Ave SW
Dickinson ND 58601

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Pipeline Leak

Release Contained: No

Reported to NRC: No

Contaminant: Crude

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

The historical contamination was discovered during hydrovac activities being performed by an outside contractor.

Risk Evaluation:

No immediate risk.

Potential Env. Impacts:

Impacted soil at site.

Action Taken/Planned:

To limit disturbance the US Forest Service provided guidance to remove impacted soil in the immediate vicinity as well as tap and drain the abandoned line to remove any remaining free liquids.

Wastes Disposal Location:

TBD - wastes will be disposed of at proper disposal facility

Other Agencies Involved:

USFS - Kim Grotte

Updates

Date: 5/15/2019 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Notes:

According to the incident summary this spill is historic contamination on USFS land. USFS will handle cleanup of site.

Updated Volume: None at the time of this update