

# General Environmental Incident Summary

**Incident:** 9229

**Notice:** 9/13/2019

**Occurred:** 9/13/2019

**DEM Incident No:**

**No Further Action:**

**Responsible Party:** Oneok Rockies Midstream

**County:** Stark

**Twp Rng Sec Qtr:** 140 97 26

**Lat Long + Method:** 46.90978 -102.89340 Interpolation from map

**Location Description:** Lodgepole Compressor Station  
3460 116th Avenue SW  
Dickinson, ND 58601

**Submitted By Info:** Levi Weltikol  
896 25th St SE  
Sidney MT 59270

**Received By Info:**

**Contact Info:** Levi Weltikol  
896 25th St SE  
Sidney MT 59270

**Affected Medium:** 03 - soil

**Near. Occupied Bldg:**

**Type of Incident:** Pipeline Leak

**Release Contained:** Yes

**Reported to NRC:** Unknown

**Contaminant:** 50/50 mix Ethylene Glycol

**Volume of Release:** 250 gallons

**Duration of Release:**

**Agriculture Related:** No

**EPA Extremely Hazardous Substance:** No

**Number of Fatalities:**

**Number of Injuries:**

**Cause of Incident:**

A leak was discovered in the piping associated with the glycol system

**Risk Evaluation:**

No immediate risks

**Potential Env. Impacts:**

Release remained on site.

**Action Taken/Planned:**

Glycol system was isolated. Remediation and repairs are being planned.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

## **Updates**

---

**Date:** 9/13/2019      **Status:** Reviewed - Follow-up Required

**Author:** Crowdus, Kory

**Notes:**

Release at non-exempt facility. Follow-up is required.

**Updated Volume:** None at the time of this update

---

**Date:** 10/18/2019      **Status:** Inspection - More Follow-up Required

**Author:** Suess, Bill

**Notes:**

Visited the site on 10/15/2019. Spoke with the RP and was informed that impacted material has been excavated and confirmation samples have been collected. Backfill material is on site. Once samples results indicate cleanup is complete, the site will be backfilled. Waiting on sampling results.

**Updated Volume:** None at the time of this update

---

**Date:** 3/24/2020      **Status:** Correspondence - More Follow-up Required

**Author:** Suess, Bill

**Notes:**

The RP has been contacted regarding sampling results. Awaiting a response.

**Updated Volume:** None at the time of this update

---

**Date:** 3/31/2020      **Status:** Correspondence - No Action Required

**Author:** Suess, Bill

**Notes:**

Received the clean-up report from the RP. Sample analysis shows residual concentrations well below the EPA Regional Screening Levels. Since this spill occurred on the Compressor Station site, no further action is warranted.

**Updated Volume:** None at the time of this update

---

**Date:** 3/31/2020      **Status:** Correspondence - No Action Required

**Author:** Suess, Bill

**Notes:**

Bill Suess sent a No Further Action letter dated March 31, 2020.

**Updated Volume:** None at the time of this update