General Environmental Incident Summary

Incident: 9396 *Notice:* 2/8/2020 *Occurred:* 2/8/2020 1615

DEM Incident No: No Further Action: ✓

Responsible Party:MPLXCounty:McKenzieTwp Rng Sec Qtr:153 97 12

Lat Long + Method:48.09578-103.09690CalculatedLocation Description:Tobacco Garden Gunslinger 372 Station

Submitted By Info: Trevor Emerick

MPLX

1515 Arapahoe Street, Suite 1600

Denver CO

Received By Info:

Contact Info:

1515 Arapahoe Street, Suite 1600

Denver CO 80202

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Inadvertent return during bore operations

Release Contained: Yes
Reported to NRC: No

Contaminant: Bentonite (water, clay, no additives)

Volume of Release: 1 barrels

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance:NoNumber of Fatalities:0Number of Injuries:0

Cause of Incident:

Inadvertent return during bore operations

Risk Evaluation:No immediate risk.

Potential Env. Impacts:

No contact with streams or bodies of water.

Action Taken/Planned:

Spill was contained with straw waddles and silt fence, and will be cleaned up by a hydrovac truck.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 2/10/2020 Status: Reviewed - Assigned to Other Agency

Author: Suess, Bill

Notes:

This incident is a bentonite release on US Forest Service land. The USFS retains jurisdiction on this site. Should the USFS request assistance, we will reopen the incident. Otherwise, no follow-up is needed.

Updated Volume: None at the time of this update