## Oil Field Environmental Incident Summary

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: OLD HICKORY 14-33TFH

Field Name: SAND CREEK

**Well File #:** 22912

Facility ID #:

County: MCKENZIE

*Twp Rng Sec Qtr:* 153 96 33 SW SW

Location Description:

Submitted By: Josey Adams

Received By:

Contact Info: Josey Adams

600 N. DAIRY ASHFORD

HOUSTON TX 77079

Affected Medium: Topsoil

**General Land Use:** Well/Facility Site **Near. Occupied Bldg:** 984.3 Feet

Nearest Water Well: 984.3 Feet

Type of Incident: Equipment Failure

Release Contained: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits2Gallons2Gallons2gallons

Brine Other

Oil

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 1/19/2017 Written Report Recd: 1/23/2017

**Risk Evaluation:**Oil to the ground

Areal Extent:

Fluid misted off the Northeast side of location. 10 foot by 30 foot area was contaminated.

Potential Env. Impacts:

Oil contaminated snow/soil

Action Taken/Planned:

Work order submitted to cleanup area

Wastes Disposal Location:

Tervita landfill

Other Agencies Involved:

## **Updates**

Date: 1/17/2017 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the report the release was not contained. Further follow up is needed.

Updated Volumes and Contaminant None at the time of this update

Date: 2/2/2017 Status: Inspection No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 4:49 2/2/2017.

Impacted area to the NE of the flare resulted in contaminated snow. This has been scraped up and there are no remaining residual impacts.

No follow-up is necessary.

**Updated Volumes and Contaminant** None at the time of this update