Oil Field Environmental Incident Summary

Incident: 20170118104721 Notice: 1/18/2017 10:47 Occurred: 1/17/2017 08:00

Responsible Party: FOUNDATION ENERGY MANAGEMENT, LLC **Well Operator:** FOUNDATION ENERGY MANAGEMENT, LLC

Well Name: PEPLINSKI 34-9
Field Name: HOOT OWL

Well File #:
Facility ID #:

County: GOLDEN VALLEY

Twp Rng Sec Qtr: 141 105 9 SE SW

20043

Location Description:

Submitted By: Tishany Jenkins

Received By:

Contact Info: Tishany Jenkins

16000 DALLAS PARKWAY, STE 875

DALLAS TX 75248

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Stuffing Box Leak
Release Contained: Yes - On Facility Site

Reported to NRC: No

Spilled Units Recovered **Units Followup** Units Oil 8 **Barrels** 8 Barrels 15 barrels 5 barrels **Brine**

Other2Barrels2BarrelsOth Rel. Contaminant:Produced Water.

Date Inspected:

Clean Up Concluded: 1/18/2017 Written Report Recd: 2/6/2017

Risk Evaluation:
Contaminated soil.
Areal Extent:

Contained on location.

Potential Env. Impacts:

Facility soil.

Action Taken/Planned:

The stuffing box rubbers have been changed and the unit is shut down. A vac truck has sucked up all free standing fluid. Clean up will continue with a steamer and vac truck to get the rest of the oil/snow cleaned up. In the spring/summer the soil will need to be drug in or scrapped up and replaced. The flow line will be cleared and Murphy switch tested and evaluated.

Wastes Disposal Location:

Approved disposal facility.

Other Agencies Involved:

Updates

Date: 1/18/2017 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the report the release remained on location. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update