

Oil Field Environmental Incident Summary

Incident: 20170118165445 **Notice:** 1/18/2017 16:54 **Occurred:** 1/17/2017 12:00

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: ELK 28-4

Field Name: INDIAN HILL

Well File #: 12910

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 153 101 28

Location Description:

Submitted By: Jordan Wolf

Received By:

Contact Info: Kaylan Dirkx
P.O Box 6506
Williston ND 58801

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels		

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None- spill was fully contained.

Areal Extent:

Potential Env. Impacts:

None- spill was fully contained within the earthen tank berm.

Action Taken/Planned:

The spill was contained within the earthen tank berm. The impacted material was recovered and hauled to an approved waste disposal facility.

Wastes Disposal Location:

IHD

Other Agencies Involved:

Updates

Date: 1/19/2017 ***Status:*** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the report the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update