

Oil Field Environmental Incident Summary

Incident: 20170317113601 **Notice:** 3/17/2017 11:36 **Occurred:** 3/16/2017 11:00

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: BEHR 30-31HTL

Field Name: REUNION BAY

Well File #: 30825

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 150 93 30

Location Description: Producing well site.

Submitted By: Teresa Van Deusen

Received By:

Contact Info: Teresa Van Deusen
3500 One Williams Center- MD38
TULSA OK 74172

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	90	Barrels	70	Barrels	90	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 3/30/2017

Written Report Recd: 1/30/2018

Risk Evaluation:

There are no immediate risks associated with this incident.

Areal Extent:

Potential Env. Impacts:

There are no immediate risks associated with this incident.

Action Taken/Planned:

Oil within lined containment is being recovered via vac truck and cycled back into production tank. Impacted soils are being hydrovaced and taken to appropriate disposal facility.

Wastes Disposal Location:

Secure Energy Services, Keene, ND

Other Agencies Involved:

Updates

Date: 3/17/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release, due to valve/piping connection leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update