

# Oil Field Environmental Incident Summary

**Incident:** 20170317144806      **Notice:** 3/17/2017    14:48    **Occurred:** 3/16/2017    20:36

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** FERTILE 76-0905H

**Field Name:** PARSHALL

**Well File #:** 29823

**Facility ID #:**

**County:** MOUNTRAIL

**Twp Rng Sec Qtr:** 151 90 9 SE SW

**Location Description:**

**Submitted By:** Danielle Dupay

**Received By:**

**Contact Info:**  
Danielle Dupay  
600 17TH ST STE 1000N  
DENVER CO 80202

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	65	Barrels	65	Barrels	65	barrels

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 3/18/2017

**Written Report Recd:** 12/19/2017

**Risk Evaluation:**

N/A

**Areal Extent:**

N/A

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

A vac truck was called immediately to remove the PW fluids along with storm water/snow melt in the SE corner of location where the incident occurred. The continuation of the snow melt water in that area will be removed with vac trucks. Once the snow melt slush water is removed that area will be assessed for further cleanup.

**Wastes Disposal Location:**

SWD

**Other Agencies Involved:**

TAT and MHA

**Updates**

---

**Date:** 3/17/2017      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

Release, due to valve/piping connection leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

**Updated Volumes and Contaminant**    None at the time of this update