

Oil Field Environmental Incident Summary

Incident: 20170524095328 **Notice:** 5/24/2017 09:53 **Occurred:** 5/23/2017 12:30

Responsible Party: PETRO-HUNT DAKOTA, LLC

Well Operator: PETRO-HUNT DAKOTA, LLC

Well Name: SHEEP FEDERAL 1A

Field Name: BOXCAR BUTTE

Well File #: 12107

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 148 102 15 SW NE

Location Description: Spill occurred at battery site to the east of location. NESW 15-148-102

Submitted By: Shawn Reisenauer

Received By:

Contact Info: Shawn Reisenauer
 390 119th Ave SW
 Killdeer ND 58640

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels		

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

All free fluids vacced up and placed back in tank. Remaining contaminated soils will be scraped up and replaced with clean materials. Fence around location has been repaired to keep livestock out. Petro-Hunt Dakota will meet with USFS to plan reclamation of abandoned battery.

Wastes Disposal Location:

IHD

Other Agencies Involved:

USFS

Updates

Date: 5/24/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release due to a tank leak was contained on the constructed well site according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update