

# Oil Field Environmental Incident Summary

**Incident:** 20170524110637      **Notice:** 5/24/2017    11:06      **Occurred:** 5/23/2017    17:00

**Responsible Party:** Kraken Operating, LLC  
**Well Operator:** KRAKEN OPERATING, LLC  
**Well Name:** WALLACE 1-6H  
**Field Name:** OLIVER  
**Well File #:** 26993

**Facility ID #:**

**County:** WILLIAMS  
**Twp Rng Sec Qtr:** 157 98 6 LO T2

**Location Description:** The spill occurred at the flare on the Northeast corner of location.

**Submitted By:** Chance Scally

**Received By:**

**Contact Info:** Pete Larsen  
9821 KATY FREEWAY, STE 460  
HOUSTON TX 77024

**Affected Medium:** Topsoil

**General Land Use:** Cultivated

**Near. Occupied Bldg:** 0.4 Mile

**Nearest Water Well:** 0.4 Mile

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0.5	Barrels				

**Brine**

**Other**

**Oth Rel. Contaminant:** None

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

right on the corner of the northeast corner of location.

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Well was shut down for the time being until high level shut off is fixed. During the next monthly pumpers meeting the importance of checking everything will be stressed.

**Wastes Disposal Location:**

Skid-steer was brought out to location and contaminated topsoil was cleaned up an put in to flare pit.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 5/24/2017      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Release, due to equipment failure, was contained on the constructed well site according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update