

Oil Field Environmental Incident Summary

Incident: 20170525073750 **Notice:** 5/25/2017 07:37 **Occurred:** 5/24/2017 17:43

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: AUSTIN 135-18H

Field Name: PARSHALL

Well File #: 27092

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 154 90 18 SE SW

Location Description:

Submitted By: Brenda Vaness

Received By:

Contact Info:
Brenda Vaness
600 17TH ST STE 1000N
DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	25	Barrels	20	Barrels	25	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/25/2017

Written Report Recd: 12/21/2017

Risk Evaluation:

N/A

Areal Extent:

Potential Env. Impacts:

N/A

Action Taken/Planned:

Pooled liquids were mopped up with absorbent pads, and a hydrovac truck was called to remove contaminated gravel. The affected area will be flushed with fresh water and sucked up to remove chlorides. The area will be monitored to determine if further clean-up is required.

Wastes Disposal Location:

To be determined

Other Agencies Involved:

Updates

Date: 5/26/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a valve/piping connection leak, was contained within the diking according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update