

Oil Field Environmental Incident Summary

Incident: 20170525130415 **Notice:** 5/25/2017 13:04 **Occurred:** 5/23/2017 05:35

Responsible Party: QC Environmental Inc
Well Operator: QC ENVIRONMENTAL SERVICES, INC.
Well Name: SPLETSTOSER 43-8
Field Name: PLAZA
Well File #: 12799
Facility ID #:
County: MOUNTRAIL
Twp Rng Sec Qtr: 152 88 8
Location Description: With in tank battery containment
Submitted By: Luke Wolf
Received By:
Contact Info: Luke Wolf
10454 1 S STREET SW
KILLDEER ND 58640

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 1 Mile

Nearest Water Well:
Type of Incident: Valve/Piping Connection Leak
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels	40	Barrels		
Other			70	Barrels		

Oth Rel. Contaminant: Rain water from containment area was recovered along with salt water.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

40x40

Potential Env. Impacts:

Soil may be contaminated

Action Taken/Planned:

Replace non position locking valve with a position locking valve.

Wastes Disposal Location:

Back into the facility disposal

Other Agencies Involved:

Updates

Date: 5/26/2017 **Status:** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: O'Gorman, Brian

Notes:

Release, due to a valve/piping connection leak, was contained within the facility diking according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update