

# *Oil Field Environmental Incident Summary*

**Incident:** 20170530111229      **Notice:** 5/30/2017    11:12      **Occurred:** 5/26/2017    14:00

**Responsible Party:** QEP ENERGY COMPANY  
**Well Operator:** QEP ENERGY COMPANY  
**Well Name:** CENTRAL TANK BATTERY 13-35X  
**Field Name:** GRAIL  
**Well File #:**  
**Facility ID #:** 225657-01  
**County:** MCKENZIE  
**Twp Rng Sec Qtr:** 150 95 35 LO T4

**Location Description:**  
**Submitted By:** Melissa Velasquez  
**Received By:**  
**Contact Info:** Gabe Holt  
 1050 17TH ST STE 500  
 DENVER CO 80265

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**  
**Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak  
**Release Contained:** Yes - On Facility Site  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	Barrels	5	Barrels		

**Brine**  
**Other**

**Oth Rel. Contaminant:**  
**Date Inspected:**

**Clean Up Concluded:**  
**Written Report Recd:**

**Risk Evaluation:**  
 None - spill was contained onsite, within berm.

**Areal Extent:**  
 NA - spill was contained onsite, within berm.

**Potential Env. Impacts:**  
 None - spill was contained onsite, within berm.

**Action Taken/Planned:**  
 Valve was closed and cleanup commenced.

**Wastes Disposal Location:**  
 Secure Energy.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 5/31/2017      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the report, the release of 5 barrels of oil was contained to the well pad. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update