

Oil Field Environmental Incident Summary

Incident: 20170721092441 **Notice:** 7/21/2017 09:24 **Occurred:** 7/21/2017 04:00

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: FERTILE 77-0905H

Field Name: PARSHALL

Well File #: 30184

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 151 90 9

Location Description:

Submitted By: Brenda Vaness

Received By:

Contact Info:
Brenda Vaness
600 17TH ST STE 1000N
DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 7/22/2017

Written Report Recd: 12/28/2017

Risk Evaluation:

N/A

Areal Extent:

Potential Env. Impacts:

N/A

Action Taken/Planned:

The liquids were sucked up with a vac truck.

Wastes Disposal Location:

EOG SWD

Other Agencies Involved:

MHA & TAT

Updates

Date: 7/24/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, this incident occurred within the MHA Nation boundaries.
Forwarded to BIA/Tribal authorities.

Updated Volumes and Contaminant None at the time of this update