

Oil Field Environmental Incident Summary

Incident: 20170721112455 **Notice:** 7/21/2017 11:24 **Occurred:** 7/20/2017 09:30

Responsible Party: LIME ROCK RESOURCES III-A, L.P.

Well Operator: LIME ROCK RESOURCES III-A, L.P.

Well Name: STATE 1-25-36H-144-97X

Field Name: CABERNET

Well File #: 18644

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 144 97 24 SW SE

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Info:
 Robyn Espinoza
 1111 BAGBY, SUITE 4600
 HOUSTON TX 77002

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	4	Barrels	3	Barrels		

Oth Rel. Contaminant: Fluid from frac communication, sand, fresh pond water and friction reducer

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Contaminated surface material

Areal Extent:

Potential Env. Impacts:

Contaminated surface material

Action Taken/Planned:

A vac truck recovered the standing fluids, the tanks have been steam cleaned and a crew will be out next week to remove all remaining contaminated materials.

Wastes Disposal Location:

Chimney Butte

Other Agencies Involved:

Updates

Date: 7/24/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update