

Oil Field Environmental Incident Summary

Incident: 20170723175302 **Notice:** 7/23/2017 17:53 **Occurred:** 7/22/2017 10:30

Responsible Party: QEP ENERGY COMPANY

Well Operator: QEP ENERGY COMPANY

Well Name: TANK BATTERY 10-18Y

Field Name: GRAIL

Well File #:

Facility ID #: 227647-01

County: MCKENZIE

TwP Rng Sec Qtr: 149 95 17 SW SW

Location Description:

Submitted By: Eric Anderson

Received By:

Contact Info: Gabe Holt
1050 17TH ST STE 500
DENVER CO 80265

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	4	Barrels	4	Barrels		

Oth Rel. Contaminant: Oil and Produced Water

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None - release contained on location

Areal Extent:

Potential Env. Impacts:

None - contained on facility location

Action Taken/Planned:

Once issue was noticed, the vic clamp on the drain was tightened and repairs are to be made. Contractor was called to vac truck up the release from the treater sump and secondary containment.

Wastes Disposal Location:

QEP approved vendor facility

Other Agencies Involved:

Updates

Date: 7/24/2017 **Status:** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update