

Oil Field Environmental Incident Summary

Incident: 20170726164002 **Notice:** 7/26/2017 16:40 **Occurred:** 7/20/2017 08:45

Responsible Party: BTA OIL PRODUCERS, LLC

Well Operator: BTA OIL PRODUCERS, LLC

Well Name: 20003 JV-P Morgan #1 SWD

Field Name: MORGAN DRAW

Well File #: 14996

Facility ID #:

County: BILLINGS

TwP Rng Sec Qtr: 144 102 32 SW NW

Location Description: This is at battery site in 31-141N-102W SWNE.

Submitted By: Kayla McConnell

Received By:

Contact Info: Kayla McConnell
104 SOUTH PECOS
MIDLAND TX 79701

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	25	Barrels
--------------	----	---------

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

Will vacuum up all recoverable. Scheduled maintenance & upkeep.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 7/26/2017 ***Status:*** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update