

Oil Field Environmental Incident Summary

Incident: 20170918115533 **Notice:** 9/18/2017 11:55 **Occurred:** 9/18/2017 11:00

Responsible Party: Kraken Operating, LLC
Well Operator: KRAKEN OPERATING, LLC
Well Name: BLAINE 1-33H
Field Name: OLIVER
Well File #: 21618
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 158 98 33 SW SE
Location Description: Off the edge of the north side of location in ditch and a light mist into farmers field.
Submitted By: Chance Scally
Received By:
Contact Info: Pete Larsen
9821 KATY FREEWAY, STE 460
HOUSTON TX 77024
Affected Medium: Topsoil
General Land Use: Cultivated
Near. Occupied Bldg: 0.3 Mile
Nearest Water Well: 0.3 Mile
Type of Incident: Equipment Failure
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2.5	Barrels	2	Barrels	0.75	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 11/1/2017

Written Report Recd: 4/27/2018

Risk Evaluation:

None

Areal Extent:

25 feet by 50 feet

Potential Env. Impacts:

None

Action Taken/Planned:

have vac truck sucking up any standing oil that is on top of the rain water.

Wastes Disposal Location:

Waste will be disposed of into our water production tank.

Other Agencies Involved:

Updates

Date: 9/18/2017 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Martin, Russell

Notes:

Release due to equipment failure, was not contained on location according to the report. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 9/25/2017 **Status:** Inspection

No Further Action:

Author: Schiermeister, Robin

Notes:

Arrived on the well pad at 9:58 on 9-21-2017. It was chilly and cloudy.

The release went off the well pad to the north. The standing water was hydro-vaced and the contaminated soil scraped up and disposed of in the flare pit. The field north of the well pad still has oily vegetation and there also appears to be oily soil on the well pad. A call was made to the party representation for confirmation samples of the field north and to dispose of the contaminated soil in the flare pit. An inspection is need at a later to date to check for revegetation and to see if the contamination was removed.

Updated Volumes and Contaminant None at the time of this update

Date: 9/5/2018 **Status:** No Further Action Requested

No Further Action:

Author: Torgerson, Brad

Notes:

On 9/5/2018 at 2:30 pm - Sunny and 67 Degrees F - I visited the Kraken Oil & Gas - Blaine 1-33H production location. I viewed the perimeter of the location and no oil stains, odors or distressed vegetation was observed. Further follow-up relating to this incident appears to be unnecessary.

Updated Volumes and Contaminant None at the time of this update