

Oil Field Environmental Incident Summary

Incident: 20170921075923 **Notice:** 9/21/2017 07:59 **Occurred:** 9/20/2017 08:20

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: VAN HOOK SECTION 15 CENTRAL FACILITY
Field Name: PARSHALL
Well File #:
Facility ID #: 219018-01
County: MOUNTRAIL
Twp Rng Sec Qtr: 152 91 15 NE NW
Location Description:
Submitted By: Brenda Vaness
Received By:
Contact Info: Brenda Vaness

600 17TH ST STE 1000N
DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	110	Barrels	110	Barrels	110	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 9/21/2017

Written Report Recd: 12/29/2017

Risk Evaluation:

N/A

Areal Extent:

Potential Env. Impacts:

N/A

Action Taken/Planned:

The LACT unit was shutdown until repairs can be made. Pooled oil was vacuumed up with vac trucks and pushed into the production tanks. Residual oil was mopped up with absorbent pads, and contaminated pad material was scraped up for disposal. The affected area will also be washed, and the liquids will be vacuumed up.

Wastes Disposal Location:

Clean Harbors, Sawyer, ND

Other Agencies Involved:

MHA & TAT

Updates

Date: 9/21/2017 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to valve/piping connection leak, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update