

# Oil Field Environmental Incident Summary

**Incident:** 20171108141909      **Notice:** 11/8/2017      14:19      **Occurred:** 11/8/2017      09:00

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** SILURIAN 6-1

**Field Name:** CHARLSON

**Well File #:** 7002

**Facility ID #:** 107002-01

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 153 95 4 SE SE

**Location Description:** Spill was at the Silurian 6-1 battery located in the SESE of 4-153-95

**Submitted By:** Shawn Reisenauer

**Received By:**

**Contact Info:** Shawn Reisenauer  
PO BOX 935  
BISMARCK ND 58502

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels	10	barrels
Brine	10	Barrels	10	Barrels	10	barrels

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 11/8/2017

**Written Report Recd:** 12/6/2017

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Pumper was onsite when gasket failed and was able to immediately shut in well and bleed pressure off of treater. All released fluids remained in dike area.

**Wastes Disposal Location:**

Secure

**Other Agencies Involved:**

BLM, US Forest Service

## ***Updates***

---

***Date:*** 11/8/2017      ***Status:*** Reviewed - Assigned to Other Agency

***No Further Action:*** ☒

***Author:*** Stockdill, Scott

***Notes:***

According to the incident summary, this spill remained on location. NDIC retains oversight.

***Updated Volumes and Contaminant***   None at the time of this update