

# Oil Field Environmental Incident Summary

**Incident:** 20171113151559      **Notice:** 11/13/2017 15:15      **Occurred:** 11/12/2017 17:30

**Responsible Party:** Crestwood Midstream

**Well Operator:**

**Well Name:**

**Field Name:**

**Well File #:**

**Facility ID #:**

**County:** DUNN

**Twp Rng Sec Qtr:** 148 94 22 NW NE

**Location Description:** Pipeline Right Of Way. 47.6287°, -102.6451°.

**Submitted By:** Joshua Swann

**Received By:**

**Contact Info:** Joshua Swann

10702 Hwy 73

Keene ND 58847

**Affected Medium:** Well/Facility Soil

**General Land Use:** Other - Described Above

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained:** Yes - On Pipeline ROW

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	270	Barrels	233	Barrels		

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

No immediate hazards or health concerns.

**Areal Extent:**

**Potential Env. Impacts:**

No Immediate impacts as the release is contained on the Right of Way, within a trench.

**Action Taken/Planned:**

Removed all free product. All contaminated material/ soil will be removed.

**Wastes Disposal Location:**

**Other Agencies Involved:**

TAT Environmental

TAT Pipeline Authority

MHA Energy

BIA

## Updates

---

**Date:** 11/14/2017    **Status:** Reviewed - Assigned to Other Agency    **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, there was a release of brine from a pipeline. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

**Updated Volumes and Contaminant**    None at the time of this update