

Oil Field Environmental Incident Summary

Incident: 20180111160449 **Notice:** 1/11/2018 16:04 **Occurred:** 1/11/2018 07:45

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: FERTILE SECTION 10 SESE CENTRAL FACILITY
Field Name: PARSHALL
Well File #:
Facility ID #: 230296-01
County: MOUNTRAIL
Twp Rng Sec Qtr: 151 90 10 SE SE
Location Description:
Submitted By: Brenda Vaness
Received By:
Contact Info: Brenda Vaness
 600 17TH ST., STE 1000N
 DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Pump Leak
Release Contained: Yes - On Facility Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	32	Barrels	60	Barrels	32	barrels
Other						

Oth Rel. Contaminant:
Date Inspected:

Clean Up Concluded: 5/5/2018
Written Report Recd: 7/13/2018

Risk Evaluation:
 N/A

Areal Extent:

Potential Env. Impacts:
 N/A

Action Taken/Planned:

Pooled liquids (production water and melted snow) were removed with a vac truck. A hydro will be used to remove additional liquids, slush, and contaminated pad material once extreme cold temperatures are not a safety threat. Following additional clean-up, the area will be monitored by EOG personnel.

Wastes Disposal Location:
 Liquids to EOG SWD and solids to be determined

Other Agencies Involved:
 MHA & TAT

Updates

Date: 1/12/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location, according to the report. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update