## **Oil Field Environmental Incident Summary**

|   | F 40  | No.600.4/02/0040  | 00.45 | 0       |               |          |
|---|---|-------------------|-------|---------|---------------|----------|
| Incident: 20180123091                       |   | Notice: 1/23/2018 | 09:15 | Occurre | ed: 1/16/2018 | 8 3;00 p |
| Responsible Party:                          | BPI-BOH, LLC                                      |                   |       |         |               |          |
| Well Operator:<br>Well Name:                | BPI-BOH, LLC                                      |                   |       |         |               |          |
| Field Name:                                 | SPRINGBROOK 1-6H SWD                              |                   |       |         |               |          |
| Well File #:                                | EPPING<br>14778                                   |                   |       |         |               |          |
| Facility ID #:                              | 01171   |                   |       |         |               |          |
| County:                                     | WILLIAMS  |                   |       |         |               |          |
| Twp Rng Sec Qtr:                            | 155 99 6  |                   |       |         |               |          |
| Location Description:                       | 100 00  | 0                 |       |         |               |          |
| Submitted By:                               | All In Oilfield Services All In Oilfield Services |                   |       |         |               |          |
| Received By:                                |   |                   |       |         |               |          |
| Contact Info:                               | Chris Dopson                                      |                   |       |         |               |          |
|   | 2520 HIGHWAY 35, STE 102                          |                   |       |         |               |          |
|   | MANASQUAN NJ 08736                                |                   |       |         |               |          |
| Affected Medium:                            | Well/Facility Soil                                |                   |       |         |               |          |
| General Land Use:                           | Well/Facility Site                                |                   |       |         |               |          |
| Near. Occupied Bldg:                        |   |                   |       |         |               |          |
| Nearest Water Well:                         |   |                   |       |         |               |          |
| Type of Incident:                           | Other   |                   |       |         |               |          |
| Release Contained:                          | Yes - On Constructed Well Site                    |                   |       |         |               |          |
| Reported to NRC:                            | No  |                   |       |         |               |          |
| Spilled                                     | Units   | Recovered         | Units |         | Followup      | Units    |
| Oil   |   |                   |       |         |               |          |
| Brine 25                                    | Gallons   |                   |       |         |               |          |
| Other                                       |   |                   |       |         |               |          |
| Oth Rel. Contaminant:                       |   |                   |       |         |               |          |
| Date Inspected:                             |   |                   |       |         |               |          |
| Clean Up Concluded:                         |   |                   |       |         |               |          |
| Written Report Recd:                        |   |                   |       |         |               |          |
| Risk Evaluation:                            |   |                   |       |         |               |          |
| None<br>Areal Extent:                       |   |                   |       |         |               |          |
|   |   |                   |       |         |               |          |
| Potential Env. Impacts None                 | 5.  |                   |       |         |               |          |
| Action Taken/Planned                        |   |                   |       |         |               |          |
| Spill was sucked back up and valve changed. |   |                   |       |         |               |          |
| Wastes Disposal Location:                   |   |                   |       |         |               |          |
| Other Agencies Involved:                    |   |                   |       |         |               |          |
|   | od.   |                   |       |         |               |          |

## **Updates**

Date: 1/23/2018 Status: Reviewed - Follow-up Required

No Further Action:

Author: Stockdill, Scott

## Notes:

Site information forwarded from NDIC. According to the NDIC, an authorized release occurred on the road terminating at this well location. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 1/31/2018 Status: Inspection

No Further Action:

Author: Stockdill, Scott

## Notes:

Arrived on location 1:47 1/31/2018.

No sign of spill at the location or on the roads leading to or from the SWD. Release entrained in roadway gravel/soil.

No follow-up necessary.

Updated Volumes and Contaminant None at the time of this update