

Oil Field Environmental Incident Summary

Incident: 20180312140737 **Notice:** 3/12/2018 14:07 **Occurred:** 3/10/2018 12:00

Responsible Party: WHITE OWL ENERGY SERVICES (US) INC.

Well Operator: WHITE OWL ENERGY SERVICES (US) INC.

Well Name: WO NEWTOWN 1

Field Name: ANTELOPE

Well File #: 90170

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 95 13

Location Description:

Submitted By: Mike Pinnell

Received By:

Contact Info: Steve Willis
P.O. BOX 1953
DICKINSON ND 58602

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1 Mile

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels	5	Barrels	5	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/15/2018

Written Report Recd: 5/29/2018

Risk Evaluation:

Majority of the spill is staining on tanks and building. A small amount of oil pooled within the tank battery berm.

Areal Extent:

Potential Env. Impacts:

Unlikely to affect ground or surface water. All affected facility soil will be removed and replaced.

Action Taken/Planned:

Spill was contained within perimeter berm. Republic Services has been called in. All standing oil will be sucked up. They will hydrovac and remove all affected soil and replace with new material. A 4" overflow line on the tank will be replaced with a 6" line. White Owl's engineering team will come up with a design to mitigate any future issues with this tank.

Wastes Disposal Location:

Republic Services in Alexander, ND.

Other Agencies Involved:

Updates

Date: 3/12/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update