Oil Field Environmental Incident Summary

Responsible Party: SLAWSON EXPLORATION COMPANY, INC. **Well Operator:** SLAWSON EXPLORATION COMPANY, INC.

Well Name: PIKE FEDERAL 7-3-2TFH

Field Name: BIG BEND Well File #: 25885

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 151 92 3 SW NW

Location Description:

Submitted By: Raymond Gorka

Received By:

Contact Info: Raymond Gorka

1675 BROADWAY STE 1600

DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Cultivated
Near. Occupied Bldg: 5300 Feet
Nearest Water Well: 5300 Feet
Type of Incident: Tank Overflow
Release Contained: Yes - Within Dike

Reported to NRC: No

Spilled **Units** Recovered **Units Followup Units** Oil 12 **Barrels** 12 Barrels **Brine** 72 **Barrels** 72 Barrels Other 25 **Barrels**

Oth Rel. Contaminant: Was water

Date Inspected:
Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:
None, tank berm is lined.
Action Taken/Planned:
Better attention to details.

Wastes Disposal Location:

Secure Services

Other Agencies Involved:

Updates

Date: 3/12/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update