

Oil Field Environmental Incident Summary

Incident: 20180314174554 **Notice:** 3/14/2018 17:45 **Occurred:** 3/14/2018 12:00

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: CANDEE 11-9H

Field Name: CHIMNEY BUTTE

Well File #: 16509

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 146 95 9

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Info: Todd Boepple
PO BOX 268870
OKLAHOMA CITY OK 73126

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	5	Barrels	10	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 3/15/2018

Written Report Recd: 3/23/2018

Risk Evaluation:

None

Areal Extent:

N/A

Potential Env. Impacts:

Well site soil

Action Taken/Planned:

Remove all visible contaminated material and replace with clean fill.

Wastes Disposal Location:

R360

Other Agencies Involved:

Called Doug at 4:40 on 3/14/2018

Updates

Date: 3/15/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update