

Oil Field Environmental Incident Summary

Incident: 20180317181558 **Notice:** 3/17/2018 18:15 **Occurred:** 3/17/2018 11:30

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: WAYZETTA SECTION 3 NENW
Field Name: PARSHALL
Well File #:
Facility ID #: 220541-01
County: MOUNTRAIL
Twp Rng Sec Qtr: 153 90 3 LO T3
Location Description:
Submitted By: Danielle Dupay
Received By:
Contact Info: Danielle Dupay

600 17TH ST., STE 1000N
 DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Tank Leak
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	80	Barrels	80	Barrels	80	barrels
Other						

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded: 5/31/2018
Written Report Recd: 7/13/2018

Risk Evaluation:
 N/A

Areal Extent:
Potential Env. Impacts:
 N/A

Action Taken/Planned:
 Vac trucks were called to remove liquids from lined containment and liquids were taken to SWD.

Wastes Disposal Location:
 SWD

Other Agencies Involved:

Updates

Date: 3/19/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update