

Oil Field Environmental Incident Summary

Incident: 20180318132009 **Notice:** 3/18/2018 13:20 **Occurred:** 3/18/2018 03:00

Responsible Party: BRUIN E&P OPERATING, LLC

Well Operator: BRUIN E&P OPERATING, LLC

Well Name: SADOWSKY 14-11-2H

Field Name: ST. ANTHONY

Well File #: 34254

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 141 96 14

Location Description:

Submitted By: Michelle Decker

Received By:

Contact Info: Tim McGhee
602 Sawyer St., Suite 710
Houston TX 77007

Affected Medium: Well/Facility Soil

General Land Use: Cultivated

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	30	Barrels	20	Barrels	30	barrels

Oth Rel. Contaminant: Oil Based Mud for drilling operations

Date Inspected:

Clean Up Concluded: 4/20/2018

Written Report Recd: 5/11/2018

Risk Evaluation:

none

Areal Extent:

On site, 300 sq feet

Potential Env. Impacts:

none, on site

Action Taken/Planned:

Air lines will be removed prior to using tanks.

Wastes Disposal Location:

20 bbls recovered will remain on site in containment and be used or disposed of with drilling operations. Additional 10 bbls that is under the mud tanks will be excavated upon completion of drilling and disposed of at approved locations

Other Agencies Involved:

Updates

Date: 3/19/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update