

Oil Field Environmental Incident Summary

Incident: 20180318195820 **Notice:** 3/18/2018 19:58 **Occurred:** 3/18/2018 09:00

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 76-22H

Field Name: PARSHALL

Well File #: 27364

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 152 90 22

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Info:
Danielle Dupay
600 17TH ST., STE 1000N
DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Treater Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels	40	Barrels	40	barrels
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/15/2018

Written Report Recd: 7/13/2018

Risk Evaluation:

N/A

Areal Extent:

Potential Env. Impacts:

N/A

Action Taken/Planned:

A vac truck was used to suck up standing liquids and a hyrovac will be used to removed contaminated rocks and wash down treater.

Wastes Disposal Location:

Liquids Shell Creek SWD and Solids Nuwalta or Secure

Other Agencies Involved:

Updates

Date: 3/19/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location according to the report. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update