Oil Field Environmental Incident Summary

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: DODGE 3C TFH
Field Name: DIMMICK LAKE

Well File #: 32978

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 151 96 17 NE NE

Location Description: 3rd party equipment-Flowback reported a leak on the clean out cover on the

blowdown tank for sand cans causing a spill in an area of 60' by 130'

resulting in a 57.93 bbl spill. The fluid contained 50/50 oil/water.

Submitted By: Josey Adams

Received By:

Contact Info: Josey Adams

600 N. DAIRY ASHFORD

HOUSTON TX 77079

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 1000 Feet
Nearest Water Well: 1000 Feet

Type of Incident: Equipment Failure

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnitsOil29Barrels29barrelsBrine29Barrels29barrels

Other

Oth Rel. Contaminant: The fluid was 50/50 produced water and oil

Date Inspected:

Clean Up Concluded: 4/4/2018
Written Report Recd: 4/4/2018

Risk Evaluation:

Produced water and oil on the ground

Areal Extent:

area of 60' by 130' resulting in a 57.93 bbl spill.

Potential Env. Impacts:

Produced water and oil on the ground

Action Taken/Planned:

Location was shut in and work order has been submitted for cleanup.

Wastes Disposal Location:

Tervita Landfill

Other Agencies Involved:

Updates

Date: 3/20/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Crowdus, Kory

Notes:

Release remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update