

Oil Field Environmental Incident Summary

Incident: 20180319115707 **Notice:** 3/19/2018 11:57 **Occurred:** 3/17/2018 17:30

Responsible Party: WHITE OWL ENERGY SERVICES (US) INC.

Well Operator: WHITE OWL ENERGY SERVICES (US) INC.

Well Name: WO NEWTOWN 1

Field Name: ANTELOPE

Well File #: 90170

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 95 13

Location Description:

Submitted By: Mike Pinnell

Received By:

Contact Info: Steve Willis
P.O. BOX 1953
DICKINSON ND 58602

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1 Mile

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Barrels			5	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/12/2018

Written Report Recd: 5/29/2018

Risk Evaluation:

No immediate risk, the oil was contained within the tank battery berm and the ground was frozen.

Areal Extent:

Potential Env. Impacts:

Very low potential for any impacts. The ground was frozen and the oil was contained within the tank battery berm.

Action Taken/Planned:

The tank was isolated. The spill was contained within the tank battery berm, on top of frozen ground. A hydrovac from Republic Services was called in to remove all of the contaminated material.

Wastes Disposal Location:

Republic Services in Alexander, ND.

Other Agencies Involved:

Updates

Date: 3/20/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update