

# Oil Field Environmental Incident Summary

**Incident:** 20180515085010      **Notice:** 5/15/2018    08:50    **Occurred:** 5/14/2018    12:35

**Responsible Party:** SLAWSON EXPLORATION COMPANY, INC.

**Well Operator:** SLAWSON EXPLORATION COMPANY, INC.

**Well Name:** MOOKA 4-29-20H

**Field Name:** BIG BEND

**Well File #:** 24218

**Facility ID #:**

**County:** MOUNTRAIL

**TwP Rng Sec Qtr:** 152 92 29 SE SW

**Location Description:** about 50' X 60' off west side of pad

**Submitted By:** Raymond Gorka

**Received By:**

**Contact Info:** Raymond Gorka  
1675 BROADWAY STE 1600  
DENVER CO 80202

**Affected Medium:** Topsoil

**General Land Use:** Cultivated

**Near. Occupied Bldg:** 2035 Feet

**Nearest Water Well:** 2035 Feet

**Type of Incident:** Fire

**Release Contained:** No

**Reported to NRC:** No

Spilled	Units	Recovered	Units	Followup	Units
---------	-------	-----------	-------	----------	-------

Oil

Brine

Other

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

Fire itself.

**Areal Extent:**

about 50' X 60'

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Fire was put out, wells closed down, area was watched to ensure fire would not restart. Other sites will be looked at closely to not let this happen elsewhere.

**Wastes Disposal Location:**

**Other Agencies Involved:**

## ***Updates***

---

***Date:*** 5/15/2018      ***Status:*** Reviewed - Assigned to Other Agency

***No Further Action:*** ☒

***Author:*** O'Gorman, Brian

***Notes:***

Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.

***Updated Volumes and Contaminant*** None at the time of this update