

# Oil Field Environmental Incident Summary

**Incident:** 20180515112736      **Notice:** 5/15/2018    11:27      **Occurred:** 5/14/2018    18:41

**Responsible Party:** WPX ENERGY WILLISTON, LLC

**Well Operator:** WPX ENERGY WILLISTON, LLC

**Well Name:** VICTOR ELK 32-29HA

**Field Name:** REUNION BAY

**Well File #:** 28588

**Facility ID #:**

**County:** DUNN

**Twp Rng Sec Qtr:** 149 93 5

**Location Description:**

**Submitted By:** Teresa Van Deusen

**Received By:**

**Contact Info:** Teresa Van Deusen  
3500 One Williams Center- MD38  
TULSA OK 74172

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Oth Rel. Contaminant:** Flash fire from gas being back fed thru air compression line.

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

All similar builds with air compression buildings are being inspected to ensure one way check valve is installed on line to ensure no similar incidents occur.

**Wastes Disposal Location:**

None

**Other Agencies Involved:**

Local Fire Department-Mandaree

## **Updates**

---

**Date:** 5/15/2018      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

According to the report, a fire occurred and was contained to the well pad. Location is within MHA Nation.

**Updated Volumes and Contaminant**    None at the time of this update