Oil Field Environmental Incident Summary

Responsible Party: WPX ENERGY WILLISTON, LLC Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: EMMA OWNER 23-14HA

Field Name: SPOTTED HORN

Well File #: 30666

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 150 94 26

Location Description:

Submitted By: Teresa Van Deusen

Received By:

Contact Info: Teresa Van Deusen

3500 One Williams Center- MD38

TULSA OK 74172

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Fire Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

None

Areal Extent:

130' X 10' along back side of berm and fence line, 60' X 30' off location.

Potential Env. Impacts:

None

Action Taken/Planned:

Pipeline contractors extinguished fire with fire extinguishers.

Wastes Disposal Location:

None

Other Agencies Involved:

Updates

Date: 5/16/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: O'Gorman, Brian

Notes:

Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.

Updated Volumes and Contaminant None at the time of this update