Oil Field Environmental Incident Summary

Responsible Party: PETRO-HUNT, L.L.C. **Well Operator:** PETRO-HUNT, L.L.C.

Well Name: STATE OF NORTH DAKOTA O 1

Field Name: KEENE Well File #: 12601

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 153 96 36

Location Description:

Submitted By: Derek Enderud

Received By:

Contact Info: Derek Enderud

PO BOX 935

BISMARCK ND 58502

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Other

Release Contained: Yes - On Facility Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 3 Barrels

Other

Oth Rel. Contaminant: Truck driver forgot to remove hose and started to drive away.

Date Inspected:
Clean Up Concluded:
Written Report Recd:

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

Contaminated surface material and well soil.

Action Taken/Planned:

Water is being sucked up off the ground and contaminated surface material is planned to be removed tonight.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 5/18/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: O'Gorman, Brian

Notes:

According to the report, 3 barrels of brine was released and contained to the facility site. NDIC

retains oversight.

Updated Volumes and Contaminant None at the time of this update