

Oil Field Environmental Incident Summary

Incident: 20180521071235 **Notice:** 5/21/2018 07:12 **Occurred:** 5/20/2018 08:30

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: BURKE 100-20H

Field Name: STANLEY

Well File #: 18163

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 155 90 20

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Info: Danielle Dupay
600 17TH ST., STE 1000N
DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	10	Barrels	10	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 7/3/2018

Written Report Recd: 7/13/2018

Risk Evaluation:

N/A

Areal Extent:

Potential Env. Impacts:

N/A

Action Taken/Planned:

A hydrovac removed standing liquids and contaminated rock

Wastes Disposal Location:

Secure, Stanley, ND

Other Agencies Involved:

Updates

Date: 5/21/2018 **Status:** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update