

Oil Field Environmental Incident Summary

Incident: 20180522160542 **Notice:** 5/22/2018 16:05 **Occurred:** 5/21/2018 21:00

Responsible Party: Hamm & Phillips
Well Operator: CONTINENTAL RESOURCES, INC.
Well Name: PASADENA 4-11HSL
Field Name: BANKS
Well File #: 34591
Facility ID #:
County: MCKENZIE
Twp Rng Sec Qtr: 152 99 11
Location Description:
Submitted By: Justin Collins
Received By:
Contact Info: Cameron Maloof

Watford City
 Watford City ND 58854

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Tank Leak
Release Contained: Yes - On Constructed Well Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	10	Barrels	10	barrels
Other						

Oth Rel. Contaminant:
Date Inspected:

Clean Up Concluded: 6/8/2018
Written Report Recd: 1/7/2019

Risk Evaluation:
 None

Areal Extent:
Potential Env. Impacts:

Well site soil

Action Taken/Planned:
 Sucked up standing fluid. Removed contaminated soil.

Wastes Disposal Location:
 TBD

Other Agencies Involved:

Updates

Date: 5/22/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Schiermeister, Robin

Notes:

Release, due to tank leak, remained on the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update