Oil Field Environmental Incident Summary

						•	
Incident: 201806051415		550 N o	otice: 6/5/2018	14:15	Occurred: 5/20/2018	3 0730	
Responsible Party:		ENDURO OPERATING, LLC					
Well Operator:		ENDURO OPERATING, LLC					
Well Name:		A.P. Houmann CTB					
Field Name:		SOUTH WESTHOPE					
Well File	#:						
Facility ID #:		402049-02					
County:		BOTTINEAU	J				
Twp Rng Sec Qtr:		162 79	19 NE SE				
Location	Description:						
Submitted By:		Scott Hunsk	or				
Received	l By:						
Contact Info:		Scott Hunskor					
		777 MAIN STREET					
		SUITE 800					
		FORT WORTH TX 76102					
Affected Medium:		Well/Facility Soil					
General Land Use:		Well/Facility Site					
Near. Oc	cupied Bldg:						
Nearest	Nater Well:						
Type of Incident:		Tank Overflow					
Release Contained:		Yes - Within Dike					
Reported to NRC:		No					
	Spilled	Units	Recovered	Units	Followup	Units	
Oil	20	Barrels	20	Barrels			
Brine	80	Barrels	80	Barrels			
Other							
Oth Rel. Contaminant:							
Date Inspected:							
Clean Up Concluded:							
Written Report Recd:							
Risk Evaluation:							
none							
Areal Extent:							
Potential Env. Impacts:							
none							
Action Taken/Planned:							
Shut wells in, get a tanker truck to empty dike. Scrape up inside dike and haul away soil and replace with fresh							
Wastes Disposal Location:							
Clean Harbors							

Other Agencies Involved:

Updates

 Date:
 6/5/2018
 Status:
 Reviewed - Assigned to Other Agency
 No Further Action:
 ✓

 Author:
 Martin, Russell
 Notes:
 Notes:
 ✓

Release due to tank overflow remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update