Oil Field Environmental Incident Summary

Incident: 20180703120904 Notice: 7/3/2018 12:09 Occurred: 7/2/2018 17:00

Responsible Party: Crestwood Midstream Partners LP

Well Operator:
Well Name:
Field Name:
Well File #:
Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 149 92 27 SE SW

Location Description: Pipeline ROW, migrated off ROW down cattle trail. 47.6891, -102.4383

decimal degrees.

Submitted By: Joshua Swann

Received By:

Contact Info: Barry Holman

10702 HWY 73

Keene ND 58847

Affected Medium: Topsoil

General Land Use: Other - Described Above

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 93 Barrels 45 Barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd:

Risk Evaluation:

No immediate risks and no explosive atmosphere.

Areal Extent:

Surface area impacted: approximately 5,600 sqft.

Potential Env. Impacts:

No impact or potential impact to surface water. Top soil on and off ROW impacted.

Action Taken/Planned:

Contained release with diking, removed all free product. Remediation plan being prepared and will be sent to TAT Environmental.

Wastes Disposal Location:

Other Agencies Involved:

MHA Energy

TAT Environmental

Updates

Date: 7/3/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report the release of brine water was not contained. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update