

Oil Field Environmental Incident Summary

Incident: 20180715232211 **Notice:** 7/15/2018 23:22 **Occurred:** 7/15/2018 01:45

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: ALFRED OLD DOG 19-18 CTB

Field Name: REUNION BAY

Well File #:

Facility ID #: 226146-01

County: DUNN

Twp Rng Sec Qtr: 150 93 30 NE NW

Location Description: Majority remained on constructed well site- a mist sprayed onto the cut slope and into field

Submitted By: Deborah Watson

Received By:

Contact Info: Deborah Watson
3500 One Williams Center- MD38
TULSA OK 74172

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	62	Barrels	60	Barrels	60	barrels
Brine	132	Barrels	130	Barrels	130	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 8/17/2018

Written Report Recd: 10/22/2018

Risk Evaluation:

There are no immediate risks at this time. All standing fluids have been removed from the location at this time.

Areal Extent:

Potential Env. Impacts:

There should not be any potential environmental impacts. It appears as if most of the spray was contained to the cut slope berm. WPX and an environmental contractor will determine if the spray impacted areas outside of the location.

Action Taken/Planned:

The wells were shut in immediately upon discovery. A hydrovac crew was brought into the location. All standing fluids were removed and additional cleanup will occur this week. The fire tube gasket will be replaced on 7/16. Containment and equipment cleaning will begin on 7/16. Impacted soil will be removed and disposed of properly.

Wastes Disposal Location:

To be determined. Potential locations included Secure Energy's Full Service Terminal in Keene, ND and Chimney Butte Landfill (PDI-R360)

Other Agencies Involved:

MHA/TAT BLM BIA

Updates

Date: 7/16/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location, according to the report. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update