

# *Oil Field Environmental Incident Summary*

**Incident:** 20180716113515      **Notice:** 7/16/2018    11:35    **Occurred:** 7/15/2018    19:00

**Responsible Party:** Slawson Exploration Co., Inc.  
**Well Operator:** SLAWSON EXPLORATION COMPANY, INC.  
**Well Name:** VAN HOOK 1-9 SWD  
**Field Name:** SANISH  
**Well File #:** 90143  
**Facility ID #:**  
**County:** MOUNTRAIL  
**Twp Rng Sec Qtr:** 152 91 9 NE NW  
**Location Description:** Well Pad  
**Submitted By:** Raymond Gorka  
**Received By:**

**Contact Info:** Raymond Gorka  
 1675 BROADWAY STE 1600  
 DENVER CO 80202

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Cultivated  
**Near. Occupied Bldg:** 4150 Feet  
**Nearest Water Well:** 4150 Feet  
**Type of Incident:** Tank Leak  
**Release Contained:** Yes - Within Dike  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	40	Barrels	40	Barrels		
<b>Other</b>						

**Oth Rel. Contaminant:**  
**Date Inspected:**  
**Clean Up Concluded:**  
**Written Report Recd:**  
**Risk Evaluation:**

None.

**Areal Extent:**

**Potential Env. Impacts:**

None, site was hydro vacced and an additional 30 bbls of muddy water/soil was vacuumed up.

**Action Taken/Planned:**

Better signage and notice of site being closed. Put up a gate next time.

**Wastes Disposal Location:**

Secure Energy Services.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 7/16/2018      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release remained on location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update