

Oil Field Environmental Incident Summary

Incident: 20180716114211 **Notice:** 7/16/2018 11:42 **Occurred:** 7/13/2018 14:37

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: FLAT TOP BUTTE 15-44

Field Name: FLAT TOP BUTTE

Well File #: 6846

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 146 101 15

Location Description:

Submitted By: Rodney Conway

Received By:

Contact Info: Rodney Conway
777 MAIN STREET
SUITE 800
FORT WORTH TX 76102

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 5 Mile

Nearest Water Well: 5 Mile

Type of Incident: Treater Popoff

Release Contained: Yes - Within Dike

Reported to NRC: No

	<i>Spilled</i>	<i>Units</i>		<i>Recovered</i>	<i>Units</i>	<i>Followup</i>	<i>Units</i>
Oil	1	Barrels		1	Barrels		

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

NA

Potential Env. Impacts:

none

Action Taken/Planned:

Empty flare pit of fresh water and oil scum and steam out .

Wastes Disposal Location:

Put in SWD

Other Agencies Involved:

Updates

Date: 7/16/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update