

# *Oil Field Environmental Incident Summary*

**Incident:** 20180716115422      **Notice:** 7/16/2018    11:54    **Occurred:** 7/13/2018    14:38

**Responsible Party:**    ENDURO OPERATING, LLC

**Well Operator:**        ENDURO OPERATING, LLC

**Well Name:**            BEICEGEL CREEK 27-42

**Field Name:**            FLAT TOP BUTTE

**Well File #:**            8468

**Facility ID #:**

**County:**                MCKENZIE

**Twp Rng Sec Qtr:**      146   101   27

**Location Description:**

**Submitted By:**        Rodney Conway

**Received By:**

**Contact Info:**        Rodney Conway  
777 MAIN STREET  
SUITE 800  
FORT WORTH TX 76102

**Affected Medium:**    Well/Facility Soil

**General Land Use:**    Well/Facility Site

**Near. Occupied Bldg:** 5 Mile

**Nearest Water Well:** 5 Mile

**Type of Incident:**     Treater Popoff

**Release Contained:**    Yes - Within Dike

**Reported to NRC:**     No

	<i>Spilled</i>	<i>Units</i>		<i>Recovered</i>	<i>Units</i>	<i>Followup</i>	<i>Units</i>
<b>Oil</b>	1	Barrels		1	Barrels		
<b>Brine</b>							
<b>Other</b>							

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

none

**Areal Extent:**

NA

**Potential Env. Impacts:**

none

**Action Taken/Planned:**

Empty flare pit of fresh water and oil, steam out if needed.

**Wastes Disposal Location:**

SWD

**Other Agencies Involved:**

## **Updates**

---

**Date:** 7/16/2018      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release remained on location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update