

# *Oil Field Environmental Incident Summary*

**Incident:** 20180716160809      **Notice:** 7/16/2018    16:08    **Occurred:** 7/15/2018    22:42

**Responsible Party:** Continental Resources Inc.  
**Well Operator:** SLAWSON EXPLORATION COMPANY, INC.  
**Well Name:** WOLVERINE FEDERAL #1-31-30H  
**Field Name:** ELM TREE  
**Well File #:** 21397  
**Facility ID #:**  
**County:** MCKENZIE  
**Twp Rng Sec Qtr:** 153 93 31  
**Location Description:**  
**Submitted By:** Raymond Gorka  
**Received By:**  
**Contact Info:** Raymond Gorka

451 106v Ave., SW  
 Killdeer ND 58640

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Pasture  
**Near. Occupied Bldg:** 9200 Feet  
**Nearest Water Well:** 9200 Feet  
**Type of Incident:** Other  
**Release Contained:** Yes - On Constructed Well Site  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>			0.1	Barrels		
<b>Brine</b>			1191	Barrels		
<b>Other</b>						

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

Mainly fresh water spraying out of well.

**Areal Extent:**

Contained on pad.

**Potential Env. Impacts:**

Spill kept on pad, dug a dike around wellhead to prevent spread of liquids..

**Action Taken/Planned:**

Need better communication with our neighbors and their completed/un-completed frack schedules.

**Wastes Disposal Location:**

Secure Energy Services..

**Other Agencies Involved:**

BLM

US Forest Service

## Updates

---

**Date:** 7/17/2018      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release remained on location, according to the report. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

**Updated Volumes and Contaminant**    None at the time of this update