

# *Oil Field Environmental Incident Summary*

**Incident:** 20180718084116      **Notice:** 7/18/2018    08:41    **Occurred:** 7/17/2018    11:00

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC

**Well Operator:** SCOUT ENERGY MANAGEMENT LLC

**Well Name:** FRYBURG 31-1

**Field Name:** FRYBURG

**Well File #:** 14997

**Facility ID #:**

**County:** BILLINGS

**Twp Rng Sec Qtr:** 139 100 31 NE NE

**Location Description:**

**Submitted By:** REBECCA Sample

**Received By:**

**Contact Info:**  
 Rebecca Sample  
 4901 LBJ FREEWAY, STE 300  
 DALLAS TX 75244

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 2500 Feet

**Nearest Water Well:** 2500 Feet

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	50	Barrels	50	Barrels		
<b>Brine</b>						
<b>Other</b>						

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

N/A

**Areal Extent:**

N/A

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

A vac truck was dispatched and sucked up the oil and returned to tank. A hot oil truck washed off the building and contaminated soil and the vac truck sucked that oil and water up and put in storage. A roustabout crew will be on location today to dig up contaminated soil, which will be disposed of.

**Wastes Disposal Location:**

R360 Chimney Butte disposal

**Other Agencies Involved:**

US Forest Service

## **Updates**

---

**Date:** 7/18/2018      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release remained on location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update