

# Oil Field Environmental Incident Summary

**Incident:** 20180718085447      **Notice:** 7/18/2018      08:54      **Occurred:** 7/17/2018      10:30

**Responsible Party:** CITATION OIL & GAS CORP.

**Well Operator:** CITATION OIL & GAS CORP.

**Well Name:** NELSON-SHARON    1H

**Field Name:** ELMS

**Well File #:** 14509

**Facility ID #:**

**County:** BOTTINEAU

**Twp Rng Sec Qtr:** 159   82   13

**Location Description:** Spill contained in dike

**Submitted By:** Lee Ann Elsom

**Received By:**

**Contact Info:** Lee Ann Elsom  
14077 CUTTEN ROAD  
PO BOX 690688  
HOUSTON TX 77269-0688

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 5 Mile

**Nearest Water Well:** 5 Mile

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	205	Barrels	200	Barrels		
-------	-----	---------	-----	---------	--	--

Other

**Oth Rel. Contaminant:** Produced water

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

NOne

**Areal Extent:**

all fluid stayed within containment

**Potential Env. Impacts:**

None

**Action Taken/Planned:**

Isolate leak- closed suction valve discharge valve downstream of line break, replaced broken nipple and other fitting on discharge side of saltwater transfer pump

**Wastes Disposal Location:**

Vacuum truck picked up water and disposed to SW disposal well

**Other Agencies Involved:**

## ***Updates***

---

***Date:*** 7/18/2018      ***Status:*** Reviewed - Assigned to Other Agency

***No Further Action:*** ☒

***Author:*** Crowdus, Kory

***Notes:***

Release remained on location, according to the report. NDIC retains oversight.

***Updated Volumes and Contaminant***   None at the time of this update